

# TECHNICAL SERVICE NOTICE

Wiring Harness 121569 or 132017  
Notice No: 129479xA

Products Affected:  
New Way Sidewinder Automated



*Driving The Difference.*

Updated: October 11, 2019

## Attention New Way Dealers and Customers:

At Scranton Manufacturing we strive to build reliable, safe equipment for the refuse industry.

We are communicating a potential performance issue with the tailgate lights on the New Way Sidewinder Automated (ASL) refuse packer. Specifically, we are addressing the performance of the wiring harness 121569 or harness 132107, which runs from the tailgate top cover sheet lights to the lower lights on the tailgate.

These harnesses are prone to chafing near the top of the tailgate on the roadside (LH side). If you find this issue we recommend the harness be replaced with a new rev harness that has a protective loom over this area.



If you are currently experiencing problems, please contact our parts department at 712-634-0063 or 712-634-0054, or email [parts@newwaytrucks.com](mailto:parts@newwaytrucks.com).

Thank you in advance for your cooperation.

Don Woerdehoff  
Service Manager